



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-354-TG
DATE : 5-Jul-2022
POLICY NO. :
VEHICLE REG. NO. : **SMC7438E**
VEHICLE MAKE : KIA CARENS 2018

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper	1	\$ 752.00	\$ 752.00 576
2	Rear Bumper Lower Cover	1	\$ 290.00	\$ 290.00 189
3	Rear Bumper Retainer RH	1	\$ 53.00	\$ 53.00
4	Rear Bumper Reflector RH	1	\$ 204.00	\$ 204.00 116
5	Rear Bumper Clip	10	\$ 5.00	\$ 50.00 30
6	Rear End Panel	1	\$ 709.00	\$ 709.00
7	Rear End Garnish	1	\$ 94.00	\$ 94.00
8	Tailamp RH	1	\$ 622.00	\$ 622.00 428
Total Special Nett				\$ 2,774.00
SPECIAL NETT				
9	Reverse Sensor	1	\$ 200.00	\$ 200.00 10%
Total Special Nett				\$ 200.00
LABOUR				
10	Spray painting Rear Bumper and Rear Bumper Cover	1	\$ 400.00	\$ 400.00 250
11	Replace Rear Area including Fitting, Cut, Weld and Re-align	1	\$ 600.00	\$ 600.00 200
12	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00 30
13	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00 30
Total Labour				\$ 1,110.00
Amount Before Excess				\$ 4,084.00
Add GST @ 7%				285.88
Total Amount Payable				\$ 4,369.88

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To dislodge damaged part(s) during resurvey
 - Parts price are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification is allowed
 - Supplementary item(s) must be resurveyed and is subject to the valuation Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749/02563571
WP' 20/7/22 @ 2pm
4/5 Resurvey after repair
taufik@lkkauto.com
02days

1205.10
510
1715.10
4591350
2days
#