



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS/FCI22006429/Kqy3m4

Date: 25/07/2022

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBK 8231R	<b>Veh. Inspected</b>	SMZ 3677L
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D22002041MFCV	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HARMINDER KAUR	<b>Assign Date</b>	05/07/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN SYLPHY (A)	<b>c.c</b>	1598
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	MNTBBAB17Z0035269	<b>Colour</b>	METALLIC RED
<b>Odometer</b>	43082 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/60 R16	BRIDGESTONE	7 mm
<b>L/H Front Tyre</b>	195/60 R16	BRIDGESTONE	7 mm
<b>R/H Rear Tyre</b>	195/60 R16	BRIDGESTONE	7 mm
<b>L/H Rear Tyre</b>	195/60 R16	BRIDGESTONE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	04/07/2022	<b>Inspection Date</b>	05/07/2022
<b>Survey held at</b>	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**