

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 25 Jul 2022

Preliminary Advice

Vehicle No	: SMD6285E	Accident Date	: 29/06/2022
Make	: AUDI A4	Policy No.	: 1800095031-03
Assignment Date	: 06/07/2022	Excess	: S\$1,100.00
Date of Inspection	: 05/07/2022	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 10,818.00	(Estimate \$10,033.00 + Supplementary \$785.00)
Revised Amount	:S\$ 6,145.00	(Inclusive of supplementary)
Check Items (Estimated)	:S\$ 1,433.00	
Total	:S\$ 7,578.00	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 122,000.00
COE / PARF Rebate	:S\$ 49,100.00
Salvage Value	:S\$
Margin for Repair	:S\$ 72,900.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.