



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LOW GARNET			Ref: CS/ASM22006441/Uqy3e2 Date: 15/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 4977P	Veh. Inspected	SLD 1527C
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M045TD	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	06/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA JAZZ (A)	c.c	1498
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JHMGK5850GX202545	Colour	RED
	Odometer	81472 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
	L/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/07/2022	Inspection Date	06/07/2022
	Survey held at	AUTOBAY PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days