



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 5737896

HP: 98888885

Estimation

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Plus photos are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date: 6/7/2022

Signature:

SMM7903B

Vehicle:

TOYOTA PRIUS

Make / Model:

INSURANCE

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRT BUMPER <i>cat</i>	1	\$ 879.00	\$ 879.00
2	FRT BUMPER SIDE RETAINER RH <i>NN</i>	1	\$ 45.00	\$ 45.00
3	FRT BUMPER DAYLIGHT COVER RH <i>NN</i>	1	\$ 52.00	\$ 52.00
4	FRT BUMPER DAYLIGHT RH <i>NN</i> <i>BR</i>	1	\$ 312.00	\$ 312.00
5	FRT BUMPER BRACKET RH <i>X</i>	1	\$ 52.00	\$ 52.00
6	HEADLAMP RH <i>X</i> <i>NN</i>	1	\$ 2,257.00	\$ 2,257.00
7	WIPER WASHER TANK <i>X</i>	1	\$ 345.00	\$ 345.00
8	FRONT FENDER RH <i>Repair</i> <i>X</i>	1	\$ 698.00	\$ 698.00
9	FRONT FENDER EMBLEM HYBRID RH <i>ABC</i>	1	\$ 52.00	\$ 52.00
10	FRONT FENDER COWLING RH <i>X</i>	1	\$ 198.00	\$ 198.00
11	FRT LOWER ARM RH <i>X</i> <i>NN</i>	1	\$ 581.00	\$ 581.00
12	FRT KNUCKLE ARM RH <i>X</i>	1	\$ 587.00	\$ 587.00
13	FRT WHEEL BEARING RH <i>X</i>	1	\$ 198.00	\$ 198.00
	TOTAL PART			\$ 6,256.00
	LIST DOWN	25%		\$ 1,564.00
	AFTER LIST DOWN			\$ 4,692.00
SPEICAL NETT				
1	FRT BUMPER CLIP SET <i>ABC</i>	1	\$ 50.00	\$ 50.00
2	FRT FENDER INNERSHIELD CLIP SET LH <i>NN</i>	1	\$ 50.00	\$ 50.00
3	FRONT WHEEL HUB CAP RH <i>SR</i>	1	\$ 100.00	\$ 100.00
4	FRONT TYRE RH <i>NN</i>	1	\$ 250.00	\$ 250.00
5	FRONT SPORTS RIM LH <i>NN</i>	1	\$ 800.00	\$ 800.00
	TOTAL AMOUNT			\$ 1,250.00
LABOUR				
	CHECK WIRING		\$ 100.00	\$ 100.00
1	R+R FRONT UNDERCARRIAGE		\$ 400.00	\$ 400.00
2	WHEEL ALIGNMENT <i>80</i>		\$ 100.00	\$ 100.00
4	R+R FRT FENDER QUARTER GLASS RH		\$ 120.00	\$ 120.00
5	REALIGN HEADLAMP		\$ 120.00	\$ 120.00
6	KNOCK		\$ 600.00	\$ 600.00
7	SPRAY		\$ 600.00	\$ 600.00
8	TOTAL AMOUNT			\$ 2,040.00
Parts Replacement Amount				\$ 5,274.25
Total Amount for Labour				\$ 2,040.00
Total Amount				\$ 7,314.25

786 ✓

X

X NN

✓

X

X

X

X

X

✓

1150

-25%

862.50

30 ✓

X

50 ✓

X

X

X

X

80

30 ✓

X

X

X

X

X

X

X

X

X

X

X

X

X

X