

Ceramic
Ceilia.

TP Alb.

8MT95786. 2019 Sept

Skoda Kodiaq 1395cc

TMBKCGNSTK8062594.

Front LH Fender Arc Garnish ^{at} 188.40 ✓

Front LH Fender Arc Garnish Clips ^{mc} 20(su) ✓

Front LH Door ^{Repis} 2897. ✓

Front LH Door Weatherstripe ^{NP} 214.90 ✓

Front LH Door Wing Mirror ^{NP} 1045.10 ✓

Front LH Door Wing Mirror Covers ^{Repis} 125.90 ✓

Rear LH Door ^{Repis} 2818. ✓

Rear LH Fender Arc Garnish ^{at} 189.40 ✓

Rear LH Fender Arc Garnish Clips ^{mc} 20(su) ✓

Rear LH Wheel Rim ^{at} 1500
750(su)

387.80 S.N: 790.

349.02

SMT95786,

Panel Beating

~~600~~ 200

Spry Painting

~~800~~ 500

Wiring.

810

~~50~~ 30

To transfer front door fittings.

150 +

To transfer rear door fittings.

150 +

To perform wheel alignment.

~~150~~ 80

total: 1949.02

4/s: 1.5K.

03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed (still is subject to final approval from Insurance Company)

Acknowledged by Repairer
Signature: _____
Date: _____