

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Senthilan Dillen Selvarajoo

Date: 12 Jul 2022

## **Preliminary Advice**

|                    |                                                                                                       |                         |                |
|--------------------|-------------------------------------------------------------------------------------------------------|-------------------------|----------------|
| Vehicle No         | : GBD7178E                                                                                            | Accident Date           | : 03/07/2022   |
| Make               | : TOYOTA HIACE                                                                                        | Policy No.              | : DMCG22005560 |
| Assignment Date    | : 06/07/2022                                                                                          | Excess                  | : S\$500.00    |
| Date of Inspection | : 07/07/2022                                                                                          | Est. Duration of Repair | : 0            |
| Inspection At      | : FORZA AUTOHAUS PTE LTD (HQ)<br>NO.39 WOODLANDS CLOSE, #01-34/35, MEGA@WOODLANDS<br>SINGAPORE 737856 |                         |                |

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |            |
|-----------------------------|------|------------|
| Repairer's Estimate (Gross) | :S\$ | 50,000.00  |
| Revised Amount              | :S\$ | Total Loss |
| Check Items (Estimated)     | :S\$ | 0.00       |
| Total                       | :S\$ | 0.00       |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

## **Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 35,000.00 |
| COE / PARF Rebate  | :S\$ | 4,599.00  |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 30,401.00 |

## **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Pending for fire investigation report