



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983
ATTN:KITTY

Ref: CC4/ASM22006463/Upa3q2

Date: 01/03/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 90P	Veh. Inspected	SMR 469H
Policy No.	P2465703	Coverage (\$)	0.00
Claim No.	S2M045VA	Excess (\$)	0.00
Assign From		Assign Date	06/07/2022

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 216I (A)	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WBA6V120305P23050	Colour	BLACK
Odometer	33504 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R17	PIRELLI	6 mm
L/H Front Tyre	205/55 R17	PIRELLI	6 mm
R/H Rear Tyre	205/55 R17	PIRELLI	6 mm
L/H Rear Tyre	205/55 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/07/2022	Inspection Date	06/07/2022
Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**