

Celine Fong (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Friday, 12 August 2022 8:18 AM
To: Celine Fong (LKKAuto)
Subject: Re: File Audit - SLU 6031T - CS/ASM22006484/Ecy3

Dear Celine,

Audit check done for SLU6031T without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Sent: Thursday, 11 August 2022 6:46 pm
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: RE: File Audit - SLU 6031T - CS/ASM22006484/Ecy3

Dear Simon,

Invoice uploaded in Views.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Sent: Thursday, 11 August 2022 5:21 PM
To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Subject: Re: File Audit - SLU 6031T - CS/ASM22006484/Ecy3

Dear Celine,

AUDIT CHECK DONE FOR SSLU6031T, FOUND SURVEYOR MARKING ON REAR BUMPER WRAPPING NEED TO REVIEW & ORIGINAL WRAPPING INVOICE NEEDED.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Celine Fong (LKKAuto) <celinefong@lkkauto.com>

Sent: Thursday, 11 August 2022 5:06 pm

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: File Audit - SLU 6031T - CS/ASM22006484/Ecy3

Dear Simon,

File for 2nd audit check with part price checked.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)