

SERVICE ESTIMATE

96847 - C00001 SL: SERVICE SALES - PC

Ms Pang Nyik Foong
58 Portchester Avenue

Singapore 556340

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Ms Pang Nyik Foong

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 06/07/2022
WIP No. . : 32138
Veh.In/Out:
*Tel.No. . : Mobile: 96322963-Alan
Reg.No. . : SLZ7564P
Reg.date . : 17/05/2018
Mileage .. : 0
Chassis No: SJKDAAH15U1060729

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT LH DOOR, REAR LH DOOR, FRT LH FENDER, FRT LH FENDER MLDING, REAR LH FENDER MLDING, WING MIRROR LH	0	4800.00	0		4,800.00	S
800	TO SPRAYPAINT ON FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, REAR LH FENDER, REAR BUMPER, WING MIRROR LH ETC	0	4800.00	0		4,800.00	S
802	TO REMOVE, REFIT & TRANSFER FRT LH DOOR COMPONENTS	0	500.00	0		500.00	S
802	TO REMOVE, REFIT & TRANSFER REAR LH DOOR COMPONENTS	0	500.00	0		500.00	S
0031	TO REPLACE FRT LH RIM	0	50.00	0		50.00	S
0031	TO REPLACE REAR LH RIM	0	50.00	0		50.00	S

SERVICE ESTIMATE

96847 - C00001 SL: SERVICE SALES - PC

Ms Pang Nyik Foong
58 Portchester Avenue

Singapore 556340

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Ms Pang Nyik Foong

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 06/07/2022
WIP No. . : 32138
Veh.In/Out:
*Tel.No. . : Mobile: 96322963-Alan
Reg.No. . : SLZ7564P
Reg.date . : 17/05/2018
Mileage .. : 0
Chassis No: SJKDAAH15U1060729

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
419	WHEEL ALIGNMENT	0	280.00	0		280.00	S
280	TO CHECK WIRING INCLUDE	0	498.00	0		498.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
NOTES	NOTES	0	0.00	0			S
	FENDER-FRONT LH Q30	1.0 EA	2250.00			2,250.00	S
	BAFFLE PLATE-FRT FEN	1.0 EA	336.10			336.10	S
	CLIP CANOE	6.0 EA	5.00			30.00	S
	FENDER-OVER,FR	1.0 EA	1450.10			1,450.10	S
	SCR-P HD PP,W	2.0 EA	3.70			7.40	S
	CLIP	2.0 EA	2.60			5.20	S
	DOOR-FRONT LH Q30	1.0 EA	3329.30			3,329.30	S
	DOOR SEAL FRT LH Q30	1.0 EA	525.80			525.80	S
	MIRROR ASSY-OUT	1.0 EA	1197.30			1,197.30	S
	COVER-MIRR BODY FRT	1.0 EA	199.20			199.20	S
	DOOR-REAR LH	1.0 EA	3163.50			3,163.50	S
	WSTRIP ASSY-RR	1.0 EA	499.50			499.50	S

SERVICE ESTIMATE

96847 - C00001 SL: SERVICE SALES - PC

Ms Pang Nyik Foong
58 Portchester Avenue

Singapore 556340

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Ms Pang Nyik Foong

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3
Inv.date. : 06/07/2022
WIP No. . : 32138
Veh.In/Out:
*Tel.No. . : Mobile: 96322963-Alan
Reg.No. . : SLZ7564P
Reg.date . : 17/05/2018
Mileage .. : 0
Chassis No: SJKDAAH15U1060729

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	FENDER OVER REAR LH	1.0 EA	1450.10			1,450.10	S
	GROM-SCR	10.0 EA	2.60			26.00	S
	RIVET	2.0 EA	12.60			25.20	S
	WHEEL-ROAD ALLOY 18"	2.0 EA	4474.10			8,948.20	S
	GRIP-OUTSIDE LH	1.0 EA	776.50			776.50	S
	ESCU-OUTSIDE,LH	1.0 EA	107.60			107.60	S
	GASKET-OUTSIDE	1.0 EA	6.10			6.10	S
	GASKET-OUTSIDE	1.0 EA	6.40			6.40	S
	BRKT-DOOR OUTSI	1.0 EA	171.90			171.90	S

			Gross Total.	35,989.40
Labour Total	11,478.00	Net.....	35,989.40	
Parts Total	24,511.40	GST @ 7.0%	2,519.26	
Package Total	0.00	Total.....	38,508.65	
			Paid.....	0.00
			Please Pay..	38,508.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated