

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS3/AGI20003837/Tvy3e2-1	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	12/07/2022	
			Co	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJR 8630R	Veh. Inspected		YP 8454R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10005810	Excess (\$)		0.00	
	Assign From	NG CHEN HOW	Assign Date		30/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN MKB37BNHRA	c.c		7684	
	Engine No.	HIDDEN	Year of Reg.		2007	
	Chassis No.	MKB37BN00034	Colour		WHITE	
	Odometer	454398 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	225/90 R17.5	BRIDGESTONE		8 mm	
	L/H Front Tyre	225/90 R17.5	BRIDGESTONE		8 mm	
	R/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE		8/8 mm	
	L/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE		8/8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/03/2020	Inspection Date		11/03/2020	
	Survey held at	MK VEHICLE ENTERPRISE				
		48 TOH GUAN ROAD EAST #04-124 SINGAPORE 608586				
5a.						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: