

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: ACS/105/009/2022/016 Date: 27<sup>th</sup> July 2022

Our Ref: CS1/SPF22006499/Gcy3e2

## M/s Automotive Engineering & MGT Division (TP)

Accident Claims Section (Spore Police Force) Police Logistics Base (PLB) 1 Hemmant Road Singapore 438675

Attn: Hafizul Farhan

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMZ 1984M

INSURED VEHICLE: QX 556K ACCIDENT DATE: 30/04/2022

We thank you for your instruction on 05/07/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMZ 1984M from M/s TY5 Consultancy.
- b) Singapore Accident Statement and Police Report of Vehicles SMZ 1984M.
- c) Colour damaged vehicle photographs of SMZ 1984M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMZ 1984M

Make & Model : Toyota C-HR Hybrid 1.8S CVT

Chassis Number : ZYX102177713

Year of Registration : 2021 Engine Capacity : 1797 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.