

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

Celine.

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 04/07/2022
TP Veh Reg No: SJL7701H

Estimate No: EST2200215
Date: 07 Jul 2022

Veh Reg No: **SMG3544L**
Make/Model: HONDA CIVIC 1.6L 5AT
Chasis No: JHMFD46209S200189
Reg. Date: 16/01/2009
Your Ref No: SJL7701H

Estimate Repair Cost to Vehicle No :SMG3544L

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1	1 PC FRT BUMPER <i>torn</i>	635.70 ✓	
2	1 PC FRT BUMPER REINFORCEMENT <i>new</i>	228.10 +	
3	1 PC FRT BUMPER SIDE RETAINER RH <i>new</i>	31.40 ✓	
4	1 PC FRT BUMPER FOG LAMP COVER RH <i>new</i>	69.90 +	
5	1 PC HEADLAMP RH <i>cut</i>	689.70 ✓	
6	1 PC HEADLAMP BRACKET RH <i>new</i>	49.10 +	
7	1 PC FRT FENDER COWLING RH <i>new</i>	134.90 ✓	
		1,838.80	
	Less 20%	367.76	1,471.04
Special Net			
8	1 SET FRT BUMPER CLIPS <i>new</i>	60.00 - 30	
9	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	40.00 - 30	
		100.00	100.00
Labour			
10	1 TO CHECK WIRING	50.00 - 30	
11	1 TO SPRAY UNDERSEAL	80.00 +	
12	1 (FRONT) TO SPRAY PAINTING	700.00 - 400	
13	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	700.00 - 300	
		1,530.00	1,530.00

730

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 04/07/2022
TP Veh Reg No: SJL7701H

Estimate No: EST2200215
Date: 07 Jul 2022

Veh Reg No: SMG3544L
Make/Model: HONDA CIVIC 1.6L 5AT
Chasis No: JHMFD46209S200189
Reg. Date: 16/01/2009
Your Ref No: SJL7701H

Estimate Repair Cost to Vehicle No :SMG3544L

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 3,101.04
	Add GST @ 7%		217.07
	Total Amount Payable		<u>S\$ 3,318.11</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND THREE HUNDRED EIGHTEEN AND CENTS ELEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian King
1/s 20/07/22
03 days

Total: 1983.36
1/s: 1850 ✓