



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2204462

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 20/07/2022
Reference CS3/III22006530/Gvy3m4
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SLB 8630B
Insured Veh. SLM 4643H
Claim No. MFL2022D0003625
Policy No. D21MFL0000447_01
Accident Date 14/05/2022
Inspection Date 08/07/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 08.07.2022 5.20pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML