



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC22006533/Evy3m4 Date: 18/08/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBD 858Y
	Policy No.	Z22VC05011770	Coverage (\$)	0.00
	Claim No.	22/22/22/VC05/026010	Excess (\$)	600.00
	Assign From	GERALD POH	Assign Date	08/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi triton l200	c.c	2477
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	MMCJNKB40FD002428	Colour	WHITE
	Odometer	208189 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205 R16C	YOKOHAMA	4 mm
	L/H Front Tyre	205 R16C	YOKOHAMA	4 mm
	R/H Rear Tyre	205 R16C	YOKOHAMA	4 mm
	L/H Rear Tyre	205 R16C	YOKOHAMA	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/07/2022	Inspection Date	08/07/2022
	Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		
5a. Remarks				
	A) THE MARKET VALUE IS S\$28,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	