



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: ONG KIAN THENG DERICK		Ref: CS/ASM22006541/Rcy3e2 Date: 09/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKA 4724H	Veh. Inspected	SMC 613L
Policy No.	GA4614907/1	Coverage (\$)	0.00
Claim No.	S2M04648	Excess (\$)	0.00
Assign From	ONG KIAN THENG DERICK	Assign Date	08/07/2022
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I30 PDE 1.4 T	c.c	1353
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	TMAH3513VJJ071055	Colour	WHITE
Odometer	48141 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	NEXEN	6 mm
L/H Front Tyre	205/55 R16	NEXEN	6 mm
R/H Rear Tyre	205/55 R16	NEXEN	6 mm
L/H Rear Tyre	205/55 R16	NEXEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/07/2022	Inspection Date	13/07/2022
Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-59 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	