Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)

Sent: Friday, 31 March 2023 11:05 AM

To: Pauline Tham

Cc: Admin A; claimsdept@sg.cntaiping.com

Subject: [SEEK MANDATE] - Your ref: SNM22D204861/C02/SGY8366C/THAMYL // LKK REF:

CC6/CTI22006570/Upa3q2 [ACCIDENT INVOLVING SGY8366C(CHINA TAIPING)

AND GBJ7544A(TP) ON 10/07/2022]

Attachments: LETTER TO OI.pdf; LKK SURVEY REPORT & PHOTOS.pdf; GBJ7544A LOD.pdf

Your ref: SNM22D204861/C02/SGY8366C/THAMYL

LKK ref: CC6/CTI22006570/Upa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING SGY8366C(CHINA TAIPING) AND GBJ7544A(TP) ON 10/07/2022

We refer to the above matter.

It is a head-to-rear collision. We are of the view that liability is not in our driver's favour.

We seek your approval to offer repairer "FASTECH AUTO PTE LTD" at \$7,455.45(all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (with 7% GST)	\$ 18,142.60	\$ 6,848.00 (\$6,400.00 + 7%GST)
2. Loss of Use (6days x \$120.00)	\$ 720.00	\$ 600.00 (6DAYS X \$100.00)
3. LTA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 18,870.05	<u>\$ 7,455.45</u>

Surveyor recommended 6days for repair.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 10/03/2023 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ: Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

