

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 17 May 2023 8:42 AM
To: ENG HUEY NI
Cc: MT_Claim_SG; Admin A
Subject: [SEEK MANDATE] -Your ref: 22/22/22/VC05/026002 // Our ref : CC4/LPC22006577/Upa3q2[ACCIDENT INVOLVING YQ3091G(LONPAC) AND GBH8788S(TP) ON 05/07/2022]
Attachments: LKK SURVEY REPORT & PHOTOS.pdf; TP LOD.pdf

Your ref: **22/22/22/VC05/026002**
Our ref : CC4/LPC22006577/Upa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING YQ3091G(LONPAC) AND GBH8788S(TP) ON 05/07/2022

We refer to the above matter.

The accident occurred when our insured driver try to swerve left while third party stopped in front of him, but insured's wing mirror still hit onto third party van (top of the brake light). We are of the view that liability is not in our driver's favour.

We seek your approval to offer repairer "**SMC AUTO ENGINEERING WORKS**" at **\$796.40(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (with 7%GST)	\$ 1,114.30	\$ 556.40 (\$520.00 + 7%GST)
2. Loss of Use (4days x \$80.00)	\$ 320.00	\$ 240.00 (3days x \$80.00)
Total	\$ 1,434.30	<u>\$ 796.40</u>

Surveyor recommended 2days for repair.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 16/05/2023 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |
S(408933)