

ComfortDelGro Engineering Pte Ltd (Co.Reg.No 199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

India International Insurance Pte Ltd (HQ)

Singapore

TP111 Ceilia.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/07/2022
Vehicle Reg. No.:	SHC1833X	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Vehicle Reg. Date:	13/12/2019
Vehicle Colour:	BLUE	Chassis No:	JTDKB3FU903090021
Engine No	2ZR2F82417		
Odometer:	279979 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	6,475.96
Miscellaneous Items	11.00
Labour	3,110.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,596.96
+ GST 7.00% (S\$)	671.79
Nett Amount (S\$)	10,268.75

This claim is handled by: **MS. LOKE YY**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jul 2022)

Parts: 144 TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC1833X/07/07/2022 09:55

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT FENDER LH <i>Dented</i>	25.00	0.00	✓ *945.30 FL
2	1		*FRT FENDER HYBRID EMBLEM LH <i>new</i>	25.00	0.00	✓ *86.50 FL
3	1		*PANEL SUB ASSY FRT DOOR LH	25.00	0.00	✓ *1,264.00 FL
4	1		*PANEL SUB ASSY RR DOOR LH <i>Dented</i>	25.00	0.00	✓ *1,258.30 FL
5	1		*REAR FENDER LH <i>Rep</i>	25.00	0.00	+ *836.70 FL
6	1		*FRT WHEEL RIM LH <i>cut</i>	25.00	0.00	✓ *1,570.55 FL
7	1		*COVER OUTER MIRROR LH	25.00	0.00	✓ *141.90 FL
8	1		*MIRROR ASSY OUTER VIEW LH <i>cracked</i>	25.00	0.00	✓ *1,728.70 FL
9	1		*ROCKER COVER PANEL GARNISH LH <i>Dented</i>	25.00	0.00	✓ *576.00 FL
10	1		*REAR FENDER PETROL STICKER LH new NEC	0.00	0.00	✓ *15.00 F
11	1		*FRT DOOR COMFORT LOGO	0.00	0.00	✓ *75.00 F
12	1		*RR DOOR COMFORT & APP STICKER <i>3 per</i>	0.00	0.00	✓ *80.00 F

F=Franchise part, L=ListItemDisc.

Sub Total (S\$) 8,577.95

- List Item Discount on L Items (S\$) 2,101.99

Total Parts (S\$) 6,475.96

ComfortDelGro Engineering Pte Ltd/SHC1833X/07/07/2022 09:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

List: 7571.25

len 25%: 5678.43

S.N: 155

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 O J/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

1050.00

2 SPRAY PAINTING CHARGE

New

1250.00

3 CHECK ALL LIGHTING & WIRING

New

30.00

4 TRANSFER OF FRT & RR DOOR

New

160.00

5 TUFF KOTE

New

60.00

Gross Labour Cost (\$\$)

3,110.00

ComfortDelGro Engineering Pte Ltd/SHC1833X/07/07/2022 09:55. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian Lj
P/P 08/08/22.

05 Days.

96893735

\$8,409.44

Total: ~~839443~~

(P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: