



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile **CS3/SMR22002470/Gqy3-1**

STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK
E4SINGAPORE 757705

Ref: ~~CS3/SMR22002470/Gqy3~~

Date: ~~16/03/2022~~ 07/07/2022

Code: SMR

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHB 1233H	Veh. Inspected	SKV 9845Z
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/03/22/2035	Excess (\$)	0.00
Assign From	HUA YEN ASHLENE LEE	Assign Date	16/03/2022 07/07/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/03/2022	Inspection Date	17/03/2022
Survey held at	SPEEDWERKZ PTE LTD 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.