

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBD2866K (Insd veh)	Model:	HINO XZU710R 4.0 D 14FT
	YQ3787H (TP veh)		WIDE CAB 5T (M)
Date of Accident:	11/07/2022		

Global Sum Settlement	:	[ ]	Yes	[ X ]	No	
Repair Estimate	:	\$	<b>8,385.76</b>			
Final Repair Cost	:	\$	3,278.69			
Loss of Use	:	\$	480.00		4.00 days at \$120.00 per day	
Rental (if any)	:	\$	0.00		days	
LTA / GIA Search Fee	:	\$	38.45			
Others:	:	\$	0.00			
	:	\$				
Final Settlement Sum	:	\$	3,797.14			

<b>Is Third Party Workshop GIA Registered?</b>				[ ]	<b>YES</b>	[ X ]	<b>NO</b>	(Kindly indicate below)
<b>A) For <u>Non GIA Registered Workshop</u>:</b>				Agreed Liability _____ 100 _____ (%)				
<b>B) For <u>GIA Registered Workshop</u>:</b>				BOLA Applicable: Yes/ No    BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ (%)				
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	Ryder Auto Pte Ltd	: \$	3,797.14
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

18 Jan  
2023

LKK Auto Consultants Pte Ltd

Date

**Please attach all the supporting documents to the form.**

**(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))**