



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: TEO KITTY		Ref: CS/ASM22006614/Rcy3e2 Date: 06/03/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XB 9033B	Veh. Inspected	GBG 813K
Policy No.	GA546521	Coverage (\$)	0.00
Claim No.	S2M046B4	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	13/07/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN NV350 2.5 5MT	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JN1MC2E26Z0007877	Colour	BLACK
Odometer	142328 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195 R15C	YOKOHAMA	6 mm
L/H Front Tyre	195 R15C	YOKOHAMA	6 mm
R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	07/07/2022	Inspection Date	13/07/2022
Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-59 AUTOBAY @ KKAI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	