

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 7 February 2023 5:18 PM
To: Sharon Tan Chow Yen; SUR
Subject: Ref: DMPC2200287H/ST | TPPD SNE7178H | Accdt invlvg SJX5955S (ECICS) & SNE7178H (DA) along CTE towards PIE exit on 08/07/2022 12:00
Attachments: SNE7178H.pdf

Dear Sharon,

Refer to email on 26.1.2023.

1. How panel has been affected due to the accident

The accident has affected 2 panels (rear bumper and Tailgate). The \$1500 coating is for whole car. We will recommend for two panels only (with consideration that the whole car has a total of 12 panels such as Front Bumper, Front LH & RH Fender, Front LH & RH Door, Rear LH & RH Door, Rear LH & RH Fender, Rear Bumper, Tailgate, Roof panel)

2. Market rate for the coating for the affected panels

The market rate based on the actual coating price did earlier of 2022 is \$1588 for whole car (12 panels), thus we recommend an amount of \$132 per panel, totalling of \$265 for 2 panels. However, please note that every shop has different pricing and it may vary from one shop to another, so our opinion to offer \$250-\$300.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Tan Chow Yen <sharon_tan@ecics.com.sg>
Sent: Thursday, 26 January 2023 10:44 AM
To: assignments <assignments@lkkauto.com>
Subject: EL Ref: DMPC2200287H/ST | TPPD SNE7178H | Accdt invlvg SJX5955S (ECICS) & SNE7178H (DA) along CTE towards PIE exit on 08/07/2022 12:00

Hi Sirs,

We refer to the third party conducted by Chen Tsue Yee.

Christine of Wearnes Automotive Pte Ltd has called and appealing for the car coating.

The coating was first done on 31/1/2022 for \$1,588.00 and the DOA is 08/07/2022.

They have provided receipt for Car coating dated 16/9/2022 and the services stated was Diamond Package – Full detailing signature on large size vehicle with pain correction + IGL Kenzo Graphene Coating x4 Redo for \$1,500

Please let us know the following:

1. How panel has been affected due to the accident
2. Market rate for the coating for the affected panels

Kindly let us have your advice latest by **30/1/2023**.

Best regards

Sharon Tan

Team Lead



DID (65) 6303 0167

Tel (65) 6206 5588

Email Sharon_Tan@ecics.com.sg

Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.