

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

ALG

Name : Meha Nathan Muthu
(94816783)

Accident Date : 29-Jun-22

Vehicle No : JSX2946 (DOR31072018)

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy <i>2 set / cur</i>	\$ 640.00
1	Fork under bracket <i>2 set / cur</i>	\$ 185.00
1	Front wheel rim <i>Weped</i>	\$ 380.00
1	Front rim shaft <i>Bnt</i>	\$ 45.00
1	Front rim bearing <i>Mel</i>	\$ 38.00
1	Front brake disc <i>11</i>	\$ 250.00
1	Handle bar <i>2 set</i>	\$ 88.00
2	Handle bar end <i>2 set</i>	\$ 80.00
1	Hand grip (1 set) <i>10.11</i>	\$ 55.00
1	Handle bar inner bracket <i>Bnt</i>	\$ 88.00
2	Side mirror <i>320</i>	\$ 110.00
1	Brake lever <i>0/5 cur</i>	\$ 42.00
1	Headlamp <i>11</i>	\$ 185.00
1	Front signals (1 set) <i>320 / cur</i>	\$ 140.00
1	Front signal lower garnish <i>cur</i>	\$ 105.00
1	Front inner cover <i>cur</i>	\$ 150.00
1	Front side inner cover (1 set) <i>cur</i>	\$ 115.00
1	Front side lower cover (1 set) <i>cur</i>	\$ 160.00
1	Fairing assy (1 set) <i>cur</i>	\$ 525.00
1	Radiator <i>2</i>	\$ 520.00
1	Front footrest bracket <i>2</i>	\$ 65.00
2	Front footrest rubbers <i>0/5 10.11</i>	\$ 70.00
1	Brake pedal <i>2</i>	\$ 65.00
2	Rear footrests <i>522</i>	\$ 80.00
2	Rear footrest brackets <i>11</i>	\$ 156.00
1	Exhaust assy <i>2</i>	\$ 585.00
1	Exhaust protector - chrome <i>cur</i>	\$ 75.00
1	Exhaust protector - black <i>grant</i>	\$ 55.00
1	Rear handle <i>cur</i>	\$ 220.00
1	Basket <i>4ray cur</i>	\$ 60.00
		\$ 5,332.00
	Less 10%	\$ 533.20
		\$ 4,798.80

not Affected
L/S # 1600/
5 days
13/7/22
Zohyphlo Affected

4012 = \$ 80

grant
present

3304

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : **Meha Nathan Muthu**
(94816783)

Accident Date : **29-Jun-22**

Vehicle No : **JSX2946 (DOR31072018)**

Vehicle Model : **Yamaha 135LC**

Estimated Repair Costs

<u>Special Net Items</u>			
1	Number plste (1 set)	121	\$ 38.00 /0
2	Fork oils	11	\$ 30.00 x
2	Fork oil seals	11	\$ 56.00 x
1	Steering cone (1 set)	121	\$ 50 90.00 ✓
1	Sticker	121	\$ 120.00 80
			\$ 334.00


S/No. Labour

1		\$	
2	To check wiring and reset headlamp focusing	\$ 11	80.00 x
3	To provide labour	\$	400.00 300
4	To repair body frame	\$ 11	350.00 x
			\$ 830.00

Grand Total

\$ 5,962.80

Singapore Dollars: Five Thousand Nine Hundred Sixty-Two and Cents: Eighty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: