

submit to us not Authorized

FASTECH AUTO PTE LTD

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: SLU 6240G

13/7/22
1/5 \$ 4100
4 days.

1PC	BONNET	DD	1024.32	\$1,429.10	✓
1PC	BONNET INNER RUBBER	11		\$66.50	X
1PC	BONNET LOGO	11	66.20	\$90.00	✓
1PC	BONNET LOCK	11		\$166.10	X
1PC	FRONT BUMPER	Re/Bon	648.10	\$651.10	✓
1PC	FRONT BUMPER CENTRE GRILLE	11		\$133.10	X
2PCS	FRONT BUMPER SIDE RETAINERS @\$69.00	11		\$138.00	✓
1PC	FRONT BUMPER REINFORCEMENT	DD		\$399.20	✓
1PC	FRONT BUMPER SPONGE	11	322.50	\$268.00	✓
1PC	FRONT GRILLE	11	135.10	\$485.10	✓
2PCS	HEADLAMPS @\$1645.10	11	472.80	\$3,290.20	✓
1PC	FRONT BRACE PANEL	11	1210.10 x 2 = 2420.20	\$151.10	X
1PC	AIR CON CONDENSER	11		\$1,486.10	X
1PC	RADIATOR	11		\$1,866.10	X
1PC	FRONT SUPPORT PANEL	11		\$745.10	X
1PC	FRONT SUPPORT PANEL TOP GARNISH	11		\$285.10	X
				\$11,649.90	

S.NETT

1SET	FRONT BUMPER CLIPS	11	\$50.00	✓
1PC	FRONT BUMPER LICENCE PLATE	11	\$50.00	40
1SET	BONNET INSULATOR CLIPS	11	\$50.00	X

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$80.00	30
TO REFILL AIR CON GAS	11	\$120.00 X
TO RESET & REPROGRAMME SYSTEM	11	\$180.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$850.00	500
TO PUTTY & SPRAY PAINTING	\$1,080.00	600
TOTAL	\$14,159.90	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

5224.22
262
3918.16
90
1150
5158.16
202
4126