

QUOTATION FOR REPAIR :FBP7987Z

Qty	Description	Repairer's Estimate
1	FRONT FOOTREST BRACKET <i>bt/</i>	140.00 /
1	REAR BRAKE PEDAL <i>bt/</i>	100.00 75
1	RHS FRONT FOOTREST <i>sea/</i>	100.00 50
1	RHS FRONT FOOTREST RUBBER <i>sea/</i>	80.00 45
1	HANDLEBAR <i>Xnn</i>	140.00 X
1	FRONT MASTER PUMP <i>OK/</i>	280.00 /
1	RHS BRAKE LEVER <i>sea/</i>	70.00 45
1	EXHAUST COVER <i>sea/</i>	120.00 75
1	EXHAUST TIP COVER <i>sea/</i>	110.00 55
2	BALANCER SET <i>hd/</i>	80.00 50
1	RHS SIDE MIRROR <i>sea/</i>	85.00 55
1	RHS REAR SIGNAL LIGHT <i>Xnn</i>	90.00 X
1	RHS FRONT SIGNAL LIGHT <i>sea/</i>	120.00 75
1	CLUTCH HOUSING <i>Xnn</i>	420.00 X
1	CLUTCH GASKET <i>Xnn</i>	80.00 X
1	ENGINE OIL <i>ne/</i>	20 50.00 S/N
1	BRAKE FLUID <i>ne/</i>	30 40.00 S/N
1	RHS Z PANEL <i>sea/</i>	140.00 100
1	RHS REAR SEAT COVER <i>sea/</i>	130.00 105
1	FRONT MUDGUARD <i>sea/</i>	135.00 85
1	RHS HEADLAMP COVER (BLACK) <i>sea/</i>	128.00 /
1	TOP BOX <i>sea/</i>	220.00 150 S/N
1	BOX RACK <i>Xnn</i>	210.00 X
1	KICK STARTER LEVER <i>Xnn</i>	120.00 X
1	REAR RHS FOOTREST BRACKET <i>Xnn</i>	120.00 X
1	REAR RHS FOOTREST <i>Xnn</i>	100.00 X

S/N - 200

	3,408.00
Less 10%	340.80
Total Part :	3,067.20
Nett items	

1363
109
1226.70

Total Nett items :	0.00
Total parts :	3,067.20

Labour Fee

FORK ALIGNMENT	220.00 160
FRONT RIM ALIGNMENT	220.00 Xnn
CHASSIS ALIGNMENT	500.00 Xnn
LABOUR FEE	800.00 350

Total Labour Fee:	1,740.00
Total parts and labour charges :	4,807.20
	7 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ramu
Hp 90010068
5 days
4/3
14/07/22 @ 1205
Resurvey after repair

1226.70
200.00
450.00
1876.70
20%

1501.76
45. \$1,500