

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX9995P*Not Authorized
Performing B4 paint***LAD2207-****85245.65**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 JUL 2022**SMX9995P**

JTDKB3FU903091508

201603575K

TOYOTA

PRIUS GEN 4

13/07/2022

G8L66412/III

09/02/2021

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 COVER, REAR BUMPER, LOWER
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, REAR FLOOR (CTR)
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 WEATHERSTRIP, BACK DOOR
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH

LIST

\$	<i>RM</i>	485.60	✓
\$	<i>RM</i>	332.70	✓
\$	<i>RM</i>	374.50	✓
\$	<i>RM</i>	118.30	X
\$	<i>RM</i>	118.30	X
\$	<i>RM</i>	132.60	X
\$	<i>RM</i>	22.00	✓
\$	<i>RM</i>	126.70	X
\$	<i>RM</i>	651.00	✓
\$	<i>RM</i>	241.90	X
\$	<i>RM</i>	175.10	X
\$	<i>MYRM</i>	229.90	✓
\$	<i>RM</i>	54.60	✓
\$	<i>RM</i>	54.60	✓
\$	<i>RM</i>	47.90	✓
\$	<i>CM</i>	913.60	✓
\$	<i>RM</i>	259.20	X
\$	<i>RM</i>	372.30	X
\$	<i>RM</i>	242.50	X
\$	<i>RM</i>	242.50	X
\$	<i>RM</i>	61.00	X
\$	<i>RM</i>	61.00	X

TOTAL \$ 5,317.80**25% \$ 1,329.45****\$ 3,988.35****Special Nett**

- 1 REAR BUMPER SIDE CLIP

\$ *RM* 60.00 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

LAD2207-**SMX9995P**

2	WINDSCREEN SEALANT	\$	na	150.00	300.00
1	WINDSCREEN MOULDING	\$	na	200.00	200.00
1	WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	300.00
1SET	PARKING AID	\$	Sn	700.00	X
1	REAR NUMBER PLATE	\$	Sn	180.00	X
1SET	REAR BUMPER CLIP	\$	na	85.00	X
1	REAR BUMPER RETAINER CLIP	\$	na	75.00	X
TOTAL		\$		1,780.00	
TOTAL PARTS		\$		5,768.35	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	300.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	600.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	600.00
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na	380.00 X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	800.00
To reinstall rear bumper parking sensor.	\$	170.00	500.00
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	200.00
To check steering geometry and computer wheel alignment	\$	na	220.00 X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	na	170.00 X
TOTAL		\$	5,300.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX9995P

LAD2207-

Over All Total \$ 11,068.35

(PART-BY-PART) Repair Days

~~20~~ Days

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX9995P**LAD2207-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY**SMX9995P**

JTDKB3FU903091508

201603575K

TOYOTA

PRIUS **GEN 4**

13/07/2022

09/02/2021

PART

- 1 PANEL SUB-ASSY, BACK DOOR

LIST

1147.8 ✓

TOTAL	\$	1,147.80
25%	\$	286.95
	\$	860.85