



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref:	CS/CTI22006669/Uqy3
3 ANSON ROAD #16-00			Date:	14/07/2022
SPRINGLEAF TOWERSINGAPORE 079909			Code:	CTI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 8333G	Veh. Inspected	SKA 1571B	
Policy No.	DMB1SNW00008142100	Coverage (\$)	0.00	
Claim No.	SNM22D204793/C02/LEWLC	Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	14/07/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/07/2022	Inspection Date	14/07/2022	
Survey held at	15 KAKI BUKIT ROAD 4 #01-05/53 BARTLEY BIZ			
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				