



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22006670/Uqy3m4 Date: 29/08/2022 Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SMS 5002H	Veh. Inspected	SMZ 4415U	
Policy No.	D22MTPV01002941	Coverage (\$)	0.00	
Claim No.	CMTD2202404/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	14/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA CX-5 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JM6KF2W7AM0674200	Colour	GREY	
Odometer	23990 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	YOKOHAMA	7 mm	
L/H Front Tyre	225/65 R17	YOKOHAMA	7 mm	
R/H Rear Tyre	225/65 R17	YOKOHAMA	7 mm	
L/H Rear Tyre	225/65 R17	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND PORTION.				
5. General Information				
Accident Date	10/07/2022	Inspect Date / Time	15/07/2022 ( 11:10 AM )	
Survey held at	HOCK MOTORS WORKSHOP NO.1 KAKI BUKIT AVE 6 #02-38 AUTOBAY @KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$16,000-\$18,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		

Report Ref No. CS3/SMO22006670/Uqy3m4

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.