

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

1/8/22 NO second hand parts.
P/P \$1476.42 informed Jans.

JIN AUTO SERVICES PTE LTD

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62894656 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

28/7/2022

W/S AIG INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR NISSAN NV350 - GBJ2741E

DOA: 07/07/2022

- TO SUPPLY
- 1 FRONT BUMPER *DS*
 - 1 FRONT BUMPER RH SIDE RETAINER *47*
 - 1 RH FOGLAMP COVER *3 and*
 - 1 RH HEADLAMP *667*

617.70

NETT ITEMS

\$	848.30	✓
\$	177.80	✓
\$	127.00	✓
\$	429.10	✓
LESS 10%	\$ 1,582.20	
	\$ (158.22)	
	\$ 1,423.98	
	\$ 30.00	20
	\$ 400.00	200
	\$ 400.00	200
TOTAL :	\$ 2,493.47	

To remove and refit electrical wiring,
To remove and replace the above damaged parts,
To spray paint on the replaced and repaired parts,

Not Allowed
4/55 p/p \$1476.42
Wk/Plk Attn 11/1 -
2 hrs
28/7/22
p/p \$1476.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1173.80
10%
1056.42
420
1476.42