



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref:	CS3/GAI22006683/Eqy3
3 TEMASEK AVENUE		Date:	14/07/2022
#16-01 CENTENNIAL TOWER			
SINGAPORE 039190		Code:	GAI
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBH 4332A	Veh. Inspected	FBT 7351L
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004193	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	13/07/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/07/2022	Inspection Date	14/07/2022
Survey held at	34 Toh Guan Road East #01-29 Singapore 608579		
Repairer	M 1 MOTORING		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			