

Celine Fong (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Friday, 15 July 2022 12:52 PM
To: Celine Fong (LKKAUTO)
Subject: Re: File Audit - SMF 9862J - CS/AIS22006698/Ecy3

Dear Celine,

Audit check done for SMF9862J, found part no.47 & 48 is duplicate. Alreay informed Steve.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Sent: Friday, 15 July 2022 12:10 pm
To: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Subject: File Audit - SMF 9862J - CS/AIS22006698/Ecy3

Dear Simon,

File for audit check.

Note: Vehicle repair part by part due to no secondhand parts available. (Vehicle more than 3 years)

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)