

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

M/S, Ao Tong

Not Authorized
 Lee
 14/7/22
 2/581000/
 2 days

VEHICLE No: SLK 2045H

1PC	TAILLAMP N/S	11	\$248.30	X
1PC	REAR BUMPER	Rep cut	\$542.20	/
1PC	REAR BUMPER SIDE RETAINER N/S	11	\$26.50	X
1PC	REAR BUMPER REFLECTOR N/S	cm	\$45.20	/
1SET	REAR BUMPER CLIPS	11	\$35.00	/
1PC	REAR END PANEL	R	\$321.00	X
		(202)	\$1,218.20	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	11 \$100.00	X
TO SPRAY RUST PROOFING	11 \$120.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$500.00	300
TO PUTTY & SPRAY PAINTING	\$800.00	400
TOTAL	\$2,868.20	

P-622-4
 202
 497.92
 770
 1267.92
 202
 1014.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: