

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 18 Jul 2022

Preliminary Advice

Vehicle No	: SMX6618Z	Accident Date	: 06/07/2022
Make	: MERCEDES-BENZ GLB200	Policy No.	: DMPG22000168
Assignment Date	: 14/07/2022	Excess	: S\$0.00
Date of Inspection	: 15/7/2022	Est. Duration of Repair	: 3
Inspection At	: ELITE AUTOMOTIVE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,068.41
Revised Amount	:S\$	4,075.94
Check Items (Estimated)	:S\$	168.44
Total	:S\$	4,244.38
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	195,000.00
COE / PARF Rebate	:S\$	71,280.00
Salvage Value	:S\$	
Margin for Repair	:S\$	123,720.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by part repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .