



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22006726/Eqy3q2	
			Date: 06/10/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJC 8990E	Veh. Inspected	XD 6695A	
Policy No.	D21MTPV01014519	Coverage (\$)	0.00	
Claim No.	CMTD2202263/MYE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	15/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA P340	c.c	11705	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	XLEP6X40005290181	Colour	YELLOW	
Odometer	53872 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	GOODYEAR	4 mm	
L/H Front Tyre	295/80 R22.5	GOODYEAR	4 mm	
R/H Rear Tyre	295/80 R22.5	GOODYEAR	4 mm	
L/H Rear Tyre	295/80 R22.5	GOODYEAR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/06/2022	Inspection Date	20/07/2022	
Survey held at	8 Sungei Kadut Way Singapore 728772			
Repairer	COMPLETE VMS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	