



Chye Thiam Maintenance Pte Ltd
14, Tampines Industrial Drive,
Singapore 528530

Attention: Owner
Contact:

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE ES 010250
Date 20/7/2022
Vehicle Number XD6695A
Make / Model SCANIA P340CB6X4MHZ
Engine Number 6714978
Chassis Number XLEP6X40005290181
Accident Date 28 Jun 2022
Policy Number 5108281586-03

Description	Qty	Unit Price	Amount
-------------	-----	------------	--------

Parts

List Items

Front Bumper L/H	✓ BT	1	S\$1,850.00	S\$1,739.00
Step Garnish L/H Lower	✓ BR (black)	1	S\$850.00	S\$807.50
Front Bumper Bracket Lower R/H	✗ NN	1	S\$325.00	S\$308.75
Step Garnish Inner L/H	✓ BR (aluminium)	1	S\$550.00	S\$522.50

Discount	10% 5%	applied	\$3,377.75
----------	--------	---------	------------

Labour

3250
-10%
2925

Labour Charge To Change All Necessary Parts	1	S\$1,250.00	S\$1,250.00	300 ✓
			\$1,250.00	

Steve (LKK)
20/7/22, 4.30pm
Without Prejudice
2 days
L/S
Resurvey After Spray

Total \$4,627.75

3225

L/S - 2580
= 2600