



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

10 EUNOS ROAD 8
SINGAPORE POST CENTRE #09-04A
SINGAPORE 408600

Ref: CS/ICS22006727/Uvy3

Date: 15/07/2022

Code: ICS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SGX 1388R
Policy No.	MPC22P0098800	Coverage (\$)	0.00
Claim No.	DMPC2200294H	Excess (\$)	250.00
Assign From	CRYSTABELLE TAN	Assign Date	15/07/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	13/07/2022	Inspection Date	15/07/2022
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A) THE MARKET VALUE IS S\$------(EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.