



Exceptional Journeys

Surveyor : STEVE LKK
Claim : TP CHINA TAIPING
DOA : 11.07.2022
Emailed : 26.09.2022, 10.45am
Date survey : 29.08.2022

VEHICLE NO : SMK 1755 L
MODEL : KIA CERATO 1.6 A L
WIP : 54162

Material	:	\$	3,413.00
Labour	:	\$	5,580.00
Sub-Total	:	\$	8,993.00
	:	\$	-
Less Excess	:	\$	-
Total	:	\$	8,993.00
GST 7%	:	\$	629.51
Grand Total	:	\$	9,622.51
Finalise By/Date	:	LOI /	23/09/2022

☒ REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 8 WORKING DAYS + 2 Days (1) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 10

☒ TP claim SLH 2142 B

☒ Claim GIA / LTA fee \$7.45

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN WEI NI	Cust No/Name	/TAN WEI NI
BLK 435 YISHUN AVENUE 6	Reg No/Reg Date	SMK1755L / 29/03/2019
#05-2106	Date In/Mileage	29/08/2022/ 32851
SINGAPORE 760435	Chassis/Package	KNAF1416MK5031074 /#
Contact No Mobile: 96607568	Engine No	G4FGJH722038
29/08/2022	Make/Model	KIA/CERATO 1.6 A L S116
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	26/09/2022/ 10:32	TLC	260 / AiTing	54162			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, BOOT LID, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1280.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR								✓ 80.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOT LID, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1100.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS TO FACILITATE REPAIR								✓ 300.00
M SUNDRY SUPPLY C&C LOGO								✓ 50.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORTIONS								✓ 40.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 50.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								✓ 280.00
M SUNDRY SUNDRIES								✓ 20.00
E PNT88000 REPLACE REAR END PANEL, REPAIR REAR FLOOR PANEL, & LH REAR FENDER								✓ 1280.00
E PNT98000 RESPRAY REAR END PANEL, REPAIR REAR FLOOR PANEL, & LH REAR FENDER								1100.00
X	COVER-RR BUMPER				1.00	✓ 651.00	00.00	651.00
X	COVER-RR BUMPER LWR				1.00	✓ 241.00	00.00	241.00
X	COVER-RR BUMPER UNDER,LH				1.00	✓ 33.00	00.00	33.00
X	COVER-RR BUMPER FOG LAMP,LH				1.00	✓ 19.00	00.00	19.00
X	LAMP ASSY-SIDE T/SIGNAL,LH				1.00	✓ 201.00	00.00	201.00
X	BEAM-RR BUMPER				1.00	✓ 318.00	00.00	318.00
X	STAY-RR BUMPER LH				1.00	✓ 65.00	00.00	65.00
X	LOGO ASSY-KIA SUB				1.00	✓ 32.00	00.00	32.00
X	EMBLEM-CERATO				1.00	✓ 28.00	00.00	28.00

This is not an official tax invoice.
This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN WEI NI	Cust No/Name	/TAN WEI NI
BLK 435 YISHUN AVENUE 6	Reg No/Reg Date	SMK1755L / 29/03/2019
#05-2106	Date In/Mileage	29/08/2022/ 32851
SINGAPORE 760435	Chassis/Package	KNAF1416MK5031074 /#
Contact No Mobile: 96607568	Engine No	G4FGJH722038
29/08/2022	Make/Model	KIA/CERATO 1.6 A L S116
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	26/09/2022/ 10:32	TLC	260 / AiTing	54162

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X PANEL ASSY-TRUNK LID	1.00	1491.00	00.00	1491.00
X PANEL ASSY-BACK	1.00	324.00	00.00	324.00
X CLIP → Supp	10.00	1.00	00.00	10.00
Z TEXT				
TP CLAIM CHINA TAIPING SLH2142B				
DOA : 11.07.22				
SURVEYOR STEVE 29.08.22				
REPAIR 05 DAYS + 03 D = 08 DAYS .				
Pro Forma				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	3,413.00	Nett	8,993.00
Labour	5,470.00	7% GST on	8993.00
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	9,622.51
Sundry/Others	110.00		
Total(w/o GST)	8,993.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO. : CHINA TAIPING

Supplementary Parts For Registration No.: SMK 1755 L

<u>Materials</u>		<u>Cost (\$)</u>
1	Clips (X10)	10.00 ✓ NEC
Total Materials		10.00
<u>Labour</u>		<u>Cost (\$)</u>
1	Replace rear end panel, repair rear floor panel, & LH rear fender	1,280.00 ✓
2	Respray rear end panel, Repair Rear floor panel, & LH rear fender	1,100.00 ✓
Total Labour		2,380.00
Taxable amount		2,390.00
7% GST		167.30
Grand total		<u>\$ 2,557.30</u>

Thank You.

Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6565 1240 / 6567 5258