

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD4655T

Make : HYUNDAI

Model : IONIQ(G2)

Date: 12/07/2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR DOOR LH / <i>buc</i>			\$ 1,789.90
1	REAR DOOR OUTER MOULDING ?			\$ 125.30
1	REAR DOOR OUTER HANDLE RH ?			\$ 108.40
	SUB TOTAL			\$ 2,023.60
	LESS 20%			\$ 404.72
	DISCOUNTED TOTAL			\$ 1,618.88
	REAR DOOR COMFORTDELGRO & APPS STICKER LH / <i>MC</i>			\$ 80.00
	FRT DOOR COMFORTDELGRO LOGO STICKER RH X <i>nn</i>			\$ 75.00
				\$ 155.00
	Labour Charge			
	PANEL BEATING			\$ 400.00
	SPRAY PAINTING CHARGE			\$ 300.00
	TUFF KOTE			\$ 80.00
	TRANSFER OF DOOR			\$ 120.00
	TOTAL LABOUR			\$ 900.00
	ESTIMATE TOTAL			\$ 2,673.88

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2171.92

20 days.
P/P
refer paint photos
Gino Qiao
12/7/22
3pm.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damage (if any) during resurvey
- Parts prices are on a "no profit, no loss" basis
- Third party surveyor to be on a "no profit, no loss" basis
- No illegal trading of parts
- Supplier to be approved and is subject to the insurance company

Acknowledged by Repairer:

Signature:

Date: