

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0545/2022/JT  
**DATE** : 30-Jun-22  
**WIP** : 30769

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

*Hi Quo Qiang*

*4 days - ok - Johnny Boo*

*27-Sep-22*

**OWNER'S NAME** : MR JEREMY KOH JOON KIAT  
**ADDRESS** : BLK 275A BISHAN ST 24  
#20-118  
SINGAPORE 571275  
**TELEPHONE** : HP +65 97649911  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1800015501-04  
**VEHICLE NO** : **SLW 4800 T**  
**MODEL CODE** : AUDI A4 SEDAN 2.0 TFSI 8W  
**MODEL YEAR** : 13/2/2018  
**ENGINE NO** : CVK 050345  
**CHASSIS NO** : WAUZZZF43JA072279  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 29-Jun-22  
**PLACE OF ACCIDENT** : 272 BISHAN ST 24

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 4800 T**

| S/N                         | NATURE OF JOBS                                                                                                                                  |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIFHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ | 480.00               | \$ <b>480.00</b>              |
| 2                           | TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.                                      | \$     | 1,050.00             | \$ <b>500.00</b>              |
| 3                           | TO RESPRAY FRONT BUMPER.                                                                                                                        | \$     | 900.00               | \$ <b>550.00</b>              |
| 4                           | <b>SUPPLEMENTARY</b>                                                                                                                            | \$     | <b>900.00</b>        | \$ <b>550.00</b>              |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                  | S/N \$ | 192.00               | \$ <b>192.00</b>              |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                 | : \$   | <b>3,522.00</b>      | \$ <b>2,272.00</b>            |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 4800 T**

|                             |                                             |     | DAMAGED PARTS & PRICES |         |                     |
|-----------------------------|---------------------------------------------|-----|------------------------|---------|---------------------|
| S/N                         | PARTS DESCRIPTION                           | QTY | S/NETT                 | REMARKS |                     |
| 1                           | FRONT BUMPER                                | 1   | \$ 2,377.00            | \$      | <del>1,429.60</del> |
| 2                           | RADIATOR GRILLE                             | 1   | \$ 1,478.00            | \$      | <b>1,182.40</b>     |
| 3                           | FRONT BUMPER GRILLE - CENTER                | 1   | \$ 219.00              |         |                     |
| 4                           | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER | 1   | \$ 254.00              |         |                     |
| 5                           | FRONT BUMPER FOAM FILLER PIECE              | 1   | \$ 139.00              | \$      | <b>110.80</b>       |
| 6                           | FRONT BUMPER REINFORCEMENT BEAM             | 1   | \$ 899.00              | \$      | <b>719.20</b>       |
| 7                           | FRONT BUMPER TOP COVER                      | 1   | \$ 143.00              |         |                     |
| 8                           | CAUTION STICKER                             | 1   | \$ 16.00               |         |                     |
| 9                           | AIR COND STICKER                            | 1   | \$ 9.00                |         |                     |
| 10                          | FRONT BUMPER BRACKET LOCK CARRIER           | 1   | \$ 154.00              |         |                     |
| 11                          | FRONT BUMPER SUPPORT - LH / RH              | 2   | \$ 64.00               |         |                     |
| 12                          | FRONT BUMPER POP RIVET                      | 4   | \$ 4.00                | \$      | <b>2.88</b>         |
| 13                          | OUTSIDE TEMPERATURE SENSOR BRACKET          | 1   | \$ 21.00               | \$      | <b>16.32</b>        |
| 14                          | RADIATOR AIR GUIDE INNER - LH / RH          | 2   | \$ 64.00               | \$      | <b>25.60</b>        |
| 15                          | RADIATOR AIR GUIDE OUTER - LH / RH          | 2   | \$ 28.00               |         |                     |
| 16                          | RADIATOR AIR GUIDE UPPER                    | 1   | \$ 19.00               |         |                     |
| 17                          | FRONT NO PLATE                              | S/N | \$ 60.00               | \$      | <b>60.00</b>        |
| 18                          | SUNDRIES                                    |     | \$ 250.00              | \$      | <b>38.96</b>        |
| <b>TOTAL SPARE PARTS</b>    |                                             | :   | \$ 6,198.00            | \$      | <b>3,585.76</b>     |
| <b>TOTAL LABOUR CHARGES</b> |                                             | :   | \$ 3,522.00            | \$      | <b>2,272.00</b>     |
| <b>GRAND TOTAL</b>          |                                             | :   | \$ 9,720.00            | \$      | <b>5,857.76</b>     |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)



## Supplementary Estimate-1

GST Reg No. 19-9902271-W

| <b>AIG Asia Pacific Insurance Pte Ltd</b><br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br>Attn: Mr. Adrian Ling - Motor Claims Dept<br><b>Tel: 6841 0055 / Fax: 6256 4315</b> |                    | <b>Estimate No.</b><br><b>Date</b><br><b>Service Advisor</b><br><b>Pages</b><br><b>Regn No</b><br><b>Model No</b> | PA/OD/0545/2022/JT<br>22-Aug-22<br>CHANG<br>1 of 1<br>SLW 4800 T<br>AUDI A4 SEDAN 2.0 TFSI |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|
| Quantity                                                                                                                                                                                      | Description        | Unit Price                                                                                                        | Amount                                                                                     |
| <b><u>Labours</u></b>                                                                                                                                                                         |                    |                                                                                                                   |                                                                                            |
| 1                                                                                                                                                                                             | TO RESPRAY BONNET. | \$ 900.00                                                                                                         | \$ <b>550.00</b>                                                                           |
| <b>GRAND TOTAL</b>                                                                                                                                                                            |                    | <b>\$ 900.00</b>                                                                                                  | <b>\$ 550.00</b>                                                                           |

For Premium Automobiles Pte Ltd

---

Authorised Signature



**PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT