Shiau Chan (LKKAuto)

From: Taufikh (LKKAuto)

Sent: Monday, 19 September 2022 11:03 AM

To: Shiau Chan (LKKAuto) **Subject:** RE: SHA7346G - Finalize

Attachments: 7346 marking.pdf; FINAL.pdf; supp.pdf

Hi Lim,

COR I/s \$5650, 3 days.

Regards Taufikh Lkk Auto

From: Lim Tien Siong [mailto:limts@cdge.com.sg]

Sent: Thursday, 21 July 2022 4:51 PM

To: Taufikh (LKKAuto)

Subject: SHA7346G - Finalize

Hi Taufikh,

Finalize at LS \$ 5,650.00 and 03 repair days. After paint and Bootlid Outer Garnish photos.

Check Items - Replaced

Bootlid Outer Garnish - \$ 1,054.71 Rear Windscreen Glass - \$ 1,758.70


Supp.Item (see attached)

Bootlid Lower Glass - Black - \$805.80

Typo error

Rear Bumper Clips - \$ 22.00 (not \$220.00)

Best Regards, Lim Tien Siong Taxi Accident Repair / ComfortDelgro Engineering Pte Ltd Off:62148398 / Fax:65468156





This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]