

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	INSURANCE (S) PL	Ī	Ref:	CS/AGI22006802/Ecy3m4	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	I	Date:	09/01/2023	
			(Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJT 8437Y	Veh. Inspected		SLN 2193Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10016407/JT	Excess (\$)		0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date		18/07/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 3	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6BN22A8H0151047	Colour		GREY	
	Odometer	385128 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R15	MICHELIN		4 mm	
	L/H Front Tyre	205/55 R15	MICHELIN		4 mm	
	R/H Rear Tyre	205/55 R15	MICHELIN		4 mm	
	L/H Rear Tyre	205/55 R15	MICHELIN		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	16/07/2022	Inspection Date)	21/07/2022	
	Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD				
		74 Kian Teck Road Singapore 628800				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: