## MFORTDELGRO ENGINEERING PTE LTD

## **EPAIR ESTIMATE\***

MAKE

VEHICLE NO SH 8094J

HYUNDAI

DATE:

18.07.22

MVA JUMANI

MARE	IONIQ	DOA:	17.07.22	<u>CHINA</u>	
MODEL	Parts Description/ Labour	Туре	Unit Price	Amount	
Qty				\$459.40 tu	
	REAR BUMPER ASSY	- **		\$451.25 4/	-
	REAR BUMPER CENTRE MOULDING			\$394.80 Xnn	
_	REAR BUMPER BEAM			\$22.00 Nei	
2 %	REAR BUMPER CLIPS			\$55.80 1X vv	1
	REAR BUMPER SIDE BRACKET RH			\$41.45 art	
1	REFLECTOR RH		0.11/12		
	SUB TOTAL		974.10	\$1,424.70	
	LESS 20%		779.28	\$284.94	
	DISCOUNTED TOTAL		, <u>, ,</u>	\$1,139.76	
	,			NET	
	REVERSE SENSOR		10		
	BUMPER MAT  LKK Auto Consultar the Repairer of the To resurvey before/afte To display damaged pa Parts prices are subject	ollowing: spray painting at(s) during result to confirmation	23-)	\$50.00 NET	Ī
	Third party survey is or     No illegal modification(		pidice" basis		
	Supplementary item(s)	must be resurv	eyed <u>and</u>	\$400.00 35	,0
	PANEL BEATING is subject to final appro	val from Insura	nce Company	\$300.00 25	ŝo
	SPRAY PAINT  Acknowledged by Repair	rer	630		
	REMOVE / REFIX REVERSE SENSOR ignature:			\$50.00	
	Taufhin 97 495749 Date:	-			
	17 1/3/11		A . O - O		
1	INP/18/7/120330pm		1639.28	\$750.00	
	TOTAL LABOUR	₹		\$750.00	
	taufhic /hhankon estimate TOTA	L	22days \$	\$2,119.76	
	is 17/120330pm TOTAL LABOUR  2 days  taufhire / hharborn ESTIMATE TOTA  // Resum byfore point				
		1			
	This is an initial estimate based on a visual inspection of the				
L	be prepared after the vehicle is surveyed by a motor Surv	eyor appoir	nted by the insurance of	company.	