



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:WINNIE		Ref: CC4/ASM22006849/Apa3q2 Date: 20/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMJ 668S	Veh. Inspected	SMF 3791U
Policy No.	GA588207	Coverage (\$)	0.00
Claim No.	S2M04700	Excess (\$)	0.00
Assign From		Assign Date	19/07/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GB71051091	Colour	BLUE
Odometer	264121 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	RAPID	6 mm
L/H Front Tyre	195/65 R15	RAPID	6 mm
R/H Rear Tyre	195/65 R15	RAPID	6 mm
L/H Rear Tyre	195/65 R15	RAPID	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/07/2022	Inspection Date	20/07/2022
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	