



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE			Ref: CC4/ASM22006853/Apa3q2 Date: 20/06/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SCQ 3292D	Veh. Inspected	SLV 4942Y	
Policy No.	GA587006	Coverage (\$)	0.00	
Claim No.	S2M046VQ	Excess (\$)	0.00	
Assign From		Assign Date	19/07/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CIVIC	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JHMF16309S202238	Colour	BLACK	
Odometer	165439 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
L/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY & UNDERCARRIAGE. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/07/2022	Inspection Date	21/07/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	