



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref: CS/SPF22006862/y3	
ACCIDENT CLAIMS SECTION			Date: 19/07/2022	
(SPORE POLICE FORCE)				
POLICE LOGISTICS BASE (PLB)				
1 HEMMANT ROAD SINGAPORE 438675			Code: SPF	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 469D		Veh. Inspected	SMK 9244S
Policy No.			Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/044		Excess (\$)	0.00
Assign From	HAFIZUL FARHAN		Assign Date	19/07/2022
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/07/2022		Inspection Date	
Survey held at	LIM YEW BOO SPRAY PAINT CO			
	BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE,			
	#01-10			
	SINGAPORE 575645.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				