



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22006885/Kny3q2 Date: 19/09/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGY 9503S	Veh. Inspected	SLL 1291P
Policy No.		Coverage (\$)	0.00
Claim No.	C10016441/JY	Excess (\$)	0.00
Assign From	SHAFAWATI MD RABU	Assign Date	20/07/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA SIENTA (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFZ28H3400026507	Colour	METALLIC SILVER
Odometer	127014 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/50 R16	YOKOHAMA	9 mm
L/H Front Tyre	195/50 R16	YOKOHAMA	9 mm
R/H Rear Tyre	195/50 R16	FALKEN	9 mm
L/H Rear Tyre	195/50 R16	FALKEN	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/07/2022	Inspection Date	05/09/2022
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	