

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029830
Tham Mun Kong

Page 1 of 2
Your ref. TP-SGY 9503S AGI
Job No. 72865
Our ref. 22.07.35
Payment
Date 19/7/2022

Attn

Vehicle No SLL 1291P
Vehicle Model : Toyota Sienta
Accident on ... 18/7/2022

Not Authorised
Phanny B Gpamy
3 days

@ 1799.70

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Tailgate	1,076.00	25.00	<i>Bt</i> 807.00 ✓
1.00	Pc	Sienta emblem	66.75	25.00	<i>na</i> 50.06 ✓
1.00	Pc	V emblem	35.50	25.00	<i>na</i> 26.63 ✓
1.00	Set	Rear windscreen mouldings	75.20	25.00	<i>na</i> 56.40 ✓
		<i>Toyota emblem</i>	<i>66.15</i>		<i>na</i> 49.61 ✓
		Special nett item:			
1.00		Rear windsreen inner seal	30.00		<i>na</i> 30.00 ✓
		Labour & Misc.			
1.00		To dismantle & refix rear windscreen	140.00		140.00 <i>1200</i> ✓
1.00		To supply sealant	40.00		40.00 ✓
1.00		To transfer reversing camera + cable	40.00		40.00 ✓
1.00		To check/clear fault codes after repair	80.00		80.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Acknowledged by Repairer:
Signature:
Date:

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0029830
Tham Mun Kong

Page: 2 of 2
Your ref.: TP-SGY 9503S AGI
Job No.: 72865
Our ref: 22.07.35
Payment
Date: 19/7/2022

Attn

Vehicle No: SLL 1291P
Vehicle Model : Toyota Sienta
Accident on ...: 18/7/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To dismantle + renew parts	250.00		250.00
1.00		To spray paint	400.00		400.00

Sub-Total 1,920.09
GST 7.00% 134.41
Total S\$ 2,054.50

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."