LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Hor, Yinrul Date: 21 Jul 2022

Preliminary Advice

Vehicle No : SMP4532S Accident Date : 16/07/2022 Make : AUDI A4 Policy No. : 1900166583-01 **Assignment Date** : 21/07/2022 **Excess** : S\$550.00

Date of Inspection : 19/07/2022 Est. Duration of Repair : 4

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,484.00
Revised Amount	:S\$	6,803.00
Check Items (Estimated)	:S\$	1,505.00
Total	:S\$	8,308.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 143,000.00 COE / PARF Rebate 58,125.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 84,875.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy covera	аge.
	Kindly let us have your authorisation.	

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: Please note that the preliminary advise amount (Revised & Check items) stated are (X) subject to consistency check, part prices and labour cost.