



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Bonnet / <i>AD</i>		600.00	✓
2	Bonnet hinges RH/LH @2*\$45 X NN		90.00	X
1	Support top panel / <i>BT</i>		350.00	✓
1	Front bumper / <i>OR</i>		350.00	✓
1	Front bumper lower cover ? BR		200.00	✓
2	Front bumper both side retainer @2*\$25 (RM) - OR		50.00	25 ✓
1	Front reinforcement / <i>BT</i>		360.00	✓
1	Front bumper sponge / <i>OR</i>		180.00	✓
1	Center grille / <i>OR</i>		300.00	✓
1	Center grille Logo badge / <i>MC</i>		55.00	✓
1	Front fender RH / <i>AD</i>		300.00	✓
1	Front fender shield RH ? X NN		90.00	X
1	Head lamp RH / <i>OR</i>		300.00	✓
2	Headlamp side lower garnish LH/RH @2*\$160 - OR		320.00	✓
1	Head lamp lower support panel RH / <i>BT</i>		60.00	✓
1	Headlamp side panel RH / <i>BT</i>		60.00	✓
1	Fog lamp RH / <i>LUT</i>		180.00	✓
1	Radiator air guide upper RH ? ✓ BR		50.00	✓
1	Radiator air guide lower RH ? X NN		50.00	X
1	Support side panel RH X NN		60.00	X
1	Front door RH (Repair refer to labour) X R		0.00	
1	Front tyre rim (Repair refer to labour) X R		0.00	3690
1	Front fender LH (Repair refer to labour) X R		0.00	+15%
1	Chassis member RH (Repair refer to labour) X R		0.00	4243.50
Part Items Total:			4005.00	
			15% 600.75	
			4605.75	
SPECIAL NETT ITEMS				
1	Front bumper clips / <i>MC</i>		30 ✓ 35.00	
1	Front fender shield clips X NN		25.00 X	
1	Center grille clips / <i>MC</i>		15 ✓ 30.00	
1	Front car plate with holder / <i>BR</i>		35.00 ✓	
1	Coolant / <i>MC</i>		20 ✓ 50.00	
1	Bonnet insulator clips X NN		35.00 X	
1	Front door company decal RH X NN		30.00 X	
SN Items Total:			240.00	
Total Parts:			4845.75	100



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH1312		Page No. 2	
Vehicle No. : GBD9133X			
Make & Model : NISSAN NV200 1.5L			
S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	900
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	1200 1000
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To carry out repair on chassis member RH/LH	300.00	? X NN
5	Remove and refit aircon condenser, radiator, related pipes and hoses, vaccum and refill aircon gas	100.00	50
Labour Total :		2860.00	1980
TOTAL (PARTS & LABOUR):		7705.75	

Steve CLKKJ
21/7/12, 3:17p

OD-MAL
EX 911-?
L/S
M AL y
5 45

= 6323.50
supp + 1265
7588.50

L/S - 6070.80
= 6050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to the relevant law
- Third party survey is on a "Time to the Police" basis
- No illegal modification is permitted
- Supplementary survey cost (if any) is subject to final approval by the relevant Company

Acknowledged by Repairer
Signature:
Date:

TTL 9315.75



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH1312
 Vehicle No. : GBD9133X
 Make & Model : NISSAN NV200 1.5L

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Intercooler BR		1100 ✓ 1400.00	
			1400.00	
			15% 210.00	
			1610.00	
	<u>SPECIAL NETT ITEMS</u>			
	Steve (LKK) 22/07/22		1100 +15% 1265	
	<u>LABOUR</u>			
Total Parts			1610.00	